

ETR STLAW ZUDGRASAH JAITMETOS TROGER MOITDEGLMI ETR

TXD008063661

REGION SITE NUMBER (to be sesign

VI

TX 13765

GENERAL INSTRUCTIONS: Complete Sections I and III through XV of this form as completely as possible. Then use the information on this form to develop a Tentarive Disposition (Section II). File this form in its entirety in the regional Hazardous Faste Log File. He sure to include all appropriate Supplemental Reports in the file. Submit a copy of the forms to: U.S. Zavironmental Protection Agency; Site Tracking System: Hazardous Faste Enforcement Tack Force (EN-333), 401 M St., SW; Vachington, DC 20460.

rector views; and traceme sys		NTIFICATION		008163	
A. SITE NAME	No. 10, 20, 20	9. STREET (or out			26 25. I
Lufkin Creosoting Comp	any)	1411 East	Lufkin A	venue	
Lufkin		TX	75901	Angelina	-
G. SITE OPERATOR INFORMATION					
I. Name.	morintoniont.			409/634-	
Danny Vines - Plant Su			-]	
P.O. Box 1207	Lufkin			\$6.37ATE	75901
A. ASALTY DWNEA THEOHMATION (} =====================================			TX	12301
I. MAME	•			1 TELEPHON	E NUMBER
Danny Vines P.	O. Box 1207	•		409/634-	-5075
1. CITY				4- 37 ATE	€ 2: F € 30€
Lufkin	·	•		ТX	75901
	ed site of Lufkin C				
Active Active	operations relocated	d to south of	town in	1978.	
1. TYPE OF OWNERSHIP					,
I . FEGERAL 2 STAT	LE T' CONLLA	L MUNICIPAL	XX S. PRIVAT	re	•
					····
A. ESTIMATE DATE OF TENTATIVE	IL TENTATIVE DISPOSITIO		ection (ast)		<u> </u>
DISPOSITION (mon. day; & yn.).		K2 Medium	1 2 LOW	T & HONE	E
		,			
C. PREPARER INFORMATION				··	
T. NAME	•	2. TELEPHONE N		1. DATE (mail	• • • • • • • • • • • • • • • • • • • •
Lisa Arceneaux		512/477-9901	L	2/0	06/87
		n information			
A. PRINCIPAL INSPECTOR INFORMA	THON	1 2. TITUE			
Lisa Arceneaux		Environme	ental Engi	ineer	
1. ORGANIZATION:		<u> </u>			E MO. (erre code & no.
Engineering-Science,	Inc. 2901 N. IH-1 Austin, TX	35 78722		512/477-9	
B. INSPECTION PARTICIPANTS	Austin, IX	10/22		312/4//-9	901
: NAME	1. GRGA	MOIT AS IM		3. TEL	[
David Wilkes	Engineering-Scie	nce, Inc.		512/477	-9901
Barry Hubbard	Engineering-Scie	nce, Inc.		512/477	-9901
Trish Kurl	Texas Water Comm	ission	-0-1	510/460	0543
Martin Turner	P.O. Box 13087.		78711	512/463	-034 <u>1</u>
C. SITE REPRESENTATIVES INTERV				AGORESS	
I, NAME	Plant Superinten		Box 120		
Danny Vines	409/634-5075	•	kin, Texas		
	9649	36/		0110505	
	ł .			SUPERF	UND FILE
		BIRE ISSEM BILLS ALES CARS		NOV 1	3 1992
		•		_	
	 		/ 	REORG	ANIZED
	Service and a service designation	T =		,	** ** * 1 fbs the top"

			INSP	ECTION INFORMATION (entinued)		
G. GENERATOR INFORMA			<u> </u>			 	·
1. NAME		ELIPHONE!	10.	3. 400			TTPE SENERATTE
Lufkin Creosotin Co.	g Ang	/634-507	75	1411 East Lufkin Lufkin, Texas 7		pentacl	hlorophenol
	1 302	7004 30	<u> </u>	Larking		- I Drudge	
						1	
L TRANSPORTER/HAUL.	er inform	ATION					
1, MAME		LIPHONEN		1. 400	P<33	MASTE TY	Detroquest de
BFI-CECOS Intl.	318	/527-685	57	P.O. Box 5416	70606	pentac	hlorophenol
				Lake Charles, LA	70606	sludge	
•							
		···					
					•		٠.
F. IF WASTE IS PROCESS	ET ON SITE	AND ALSO	HIPO	13 ТЭ, ОТНЕЯ SITES, ICENT	TIEY OF THE FACILITY	125 USED 208	DISPOSAL.
1. MAME		LEPHONE			3. ACCRE11		
		·		P.O. Box 5416			
BFI-CECOS Intl.	318	/527-685	57	Lake Charles, LA	70606		
						v.	
<u> </u>							· ************************************
G. CATE OF INSPECTION	715	e of these	C = 10 ×	I. ACCESS GAINED BY: (ar		10 41 (2000)	
(Com day, A 77)				XX I. PERMISSION	Z PARRANT	,, <u>,</u>	
Ja WEATHER (departs)	86 1:3	3 - 5:20	J	CITE IS CERTIFICA			
Clear and hot							
			ΓV	SAMPLING INFORMATIO	134.	····	
A. Mark 'I' for the types	rof sample	= taken and		te where they have been s	كالبدادات الأناك المنبطة خالجة المتفولي	other EPA lat	, contractor,
ett. and estimate whe							
•		2.5.4404.2					4.0478
1. SAMPLE TYPE		TAKEN (merk 'Z')		1.3AMFC	E SENT TO:		ACSULTS AULICAGE
L GROUNGWATER							
					· · · · · · · · · · · · · · · · · · ·	 	<u> </u>
RET AN EDATRUL &				.*			
							1
G. WASTE							,
		<u> </u>		·			
d AIM			r e				
& RUNGFF					·		
6 3916.L.				<u> </u>		٠.	
د بادان		(4)	Engi	neering-Science Bancroft Way, Be	Laboratory	710	9/20/86
		X (4)	600	Bancroit way, Be	IRELEY, CA 94	110	8/20/86
N VESETATION				* .	•		
L GTHER(specify)		<u> </u>	1				
							i
8. FIELD MEASUREMENT	S TAKEN /	.d., rediaecti	rity. es	placivity, PH, etc.)			<u>.</u>
1. 1794				OF MEASUREMENTS	3	. # EŠUL 71	
					· ·		
None				·			
· Pr to contact the	ರಣದಲ್ಲ						
FUND (FILE	nanyo						
							
100000	MOM				 		
	. :						
1		· ·		and the second s			

	Onthings From Page 1	-			_	ين المساور و المساور		كالمراجع والمستعدد والمستوانية في يهون في مواليات والموادية				
<u> </u>	1		[V. SAME	LING INFOR	M	ATION (continued)						
4 ×	PHOTOS						•					
1	. Type of Photos			2. PHOTOS I	N C	USTODY OF:						
L	■ 1. ARPUNO ■ 1. ARP	ITAL	·	See At	t	achment D						
0.	SITE MAPPEOT											
	X YES SPECIFY LOCATION	3 F	MAPS: See At	tachment	D							
L			Site s	ketch, ar	eä	map and floodplain m	nar					
E.	COORDINATES											
J - 1	. Latitude (deg-min-sec.)				1	LONGITUDE (dego-mino-seco)						
1	31°20'10" N 94°43'00" W											
_				V. SITE INFO	-		-					
Α.	A. SITE STATUS											
	I. ACTIVE (Those inductries of	-	XX 2 INACTIV	E (Those	1	1. OTHER(specify):		•				
	iumicipal situa unich ero being uz	ed.	sites which no			(These sites that include such inc						
	or weate treement, storege, or dis n e continuing besix, even il intre		al restate)			where no require or continuing use has equired.).	46	THE TITE IOF MASTE SISBOARI				
٩	tuenti (y.)							•				
3.	IS GENERATOR ON SITE?				<u> </u>							
1 _		eci f	y generator's low-d	Haie SIC Codel:		2491						
ľ `												
	AREA OF SITE (in agree)		O. ARE THERE		104	Pud 01777						
-	8 acres											
	o acres		☐ 1. NO	XX 2 753/4	pe	an old barn						
 		<u> </u>										
<u> -</u>						OF SITE ACTIVITY						
	icate the major site activity():	44)	and details relati	ag to each ac	21.7	ity by marking 'X' in the appro-	on:	ste poxes.				
Ĥ	A. TRANSPORTER	<u> </u>	B. STOR	ER	×.	C. TREATER	X.	G. DISPOSER				
П	1.RAIL		1. #16.2			I. FILTRATION	÷	1. LANOFILL				
П	2. SHIP		Z. SURFACE IMPO	UNGMENT		Z.INCINERATION		2. LANGFARM				
	J. BARGE		3. ORUMS			1. VOLUME REDUCTION		1. OPEN GUMP				
H	4 TRUCK		4. TANK, ABOVE	SACUNO	-	4.RECYCLING/RECOVERY	X	4. SURFICE IMPOUNDMENT				
	S. PIPELINE	-	S. TANK, BELOW		 	S. CHEMUTHYS TREATMENT	1	S. MIGNIGHT GUMPING				
	4. OTHER(aposity)		1. OTHER (specify		-	4. SIGLOGICAL TREATMENT	 	4. INCINERA TION				
 	; •• • • • • • • • • • • • • • • • • •	-		, -	-	7. HASTE OIL REPROCESSING	-	T. UNGERGROUND INJECTION				
					-	4.3GLYENT RECOVERY	 	1. OTHER(specify):				
		1			 	9.0THER(specify):	-					
l	•				_	THE CANAL PROPERTY.	l	G Attinghment A				
I							ļ	See Attachment A				
								•				
1												
-	SUPPLEMENTAL APPORTS: "	171=	site falls within an	v of the estima	77,-	s listed below, Supplemental Repor	(Ex.	nust be completed. Indicate				
_	which Supplemental Reports you							Andrew Company of the				
_	TI. STORAGE	9 - 1 AL	CINERATION [T 3: LANDFIL		KXI 4 SURFACE		DEEP WELL				
۱ ـ	المناء المالمان	- 15			-	MENT LIMEOUNDMENT	3.	40 haydii FT 17 Gi 188 hiji				
	4. CHEM/BIO/	٠. نـ	ANOFARM [_ al open ou	ME	9. TRANSPORTER .	10	. RECYCLOR/RECLAIMER				
	7.1	41	VTL WA	STE RELAT	ΞD	INFORMATION						
۸.	WASTE TYPE											
] I. LIQUID XX:	Ļ. S	orio g	A stnoce		4. GAS						
								·				
9.	WASTE CHARACTERISTICS											
	1. CORROSIVE	2.10	NITABLE [J. RAGIGAC	71	ve 🔲 4. Highly volatile -		•				
Ø	a. Toxic	s. a	EACTIVE	7. INERT		S. FLAMMABLE		• .				
_	-		•					we will be a second of the sec				
	9. OTHER/seedles:		·			<u> </u>	_	· · · · · · · · · · · · · · · · · · ·				
	WASTE CATEGORIES	. و	ecify items such as	manifests, im		todes, etc. below-						
l '	manifest of pentachl						,					
1	"" TITLE OF DELICACITY			.,								

EPA Form T2070-3 (10-79)

PAGE 3 OF 10

Continue On Reverse

L. WASTE RELATED INFORMATION (continue) 2. Estimate the amount (specify unit of measure) of wester by category; mark 'X' to indicate which wester are present.															
2. Estimate the	- AUROU	at (specify unit de s. Oil	meas		weste by cz LVENTS	1000		EMICYT H . Z. sc		30	e which was a squict		364	3436. (, 27%	e e
AMOUNT		AMOUMT	j.	MOUNT		1			-	-	-QUAT		1	40.4.F	الأسينسنشية.
10	9 ਵਵੇਂ	unknown		unkno	own	1	unkno				unknown	1.00	!	unkno	
tons								-4.74						N, F 32, OC	-1676
TE SIGMENTS		TI GILY		71136	LOGEMATEC LVENTS	, ,	11 .41	33		1	111 PLYASM			i,,, ua sc:	4. CEU T.
CAP METALS		21 OTHER (speed	4772	12 70	ガードレンロル T Lyents	-	123 476	XUMG UGP1	1		121 4184570	3		121 = 05P	TAL.
(3) POTW	,	·	-	13197	west (specify)	*	131 671	EDIT IN	`.		(3) WEWAS	mu<	<u> </u> 	(3) A A Q1Q	ACTIVE
THE SCHOOLS	-						141.083	TICICE	3		144 DM1441	SMCL ?	1	(4) MEMIC	1 3 A.C.
XX ISSOTHER CO.	-aity)I					ſ	(3) 37 (3/1243			12, NOMETER	eous	_	11 STHE	A (20 mg/)
pentachlor phenol slud					. •		(4) C.Y.	.mo€			IN OTHER!		<u>.</u>		
(tank botto	ms)					7	X (7) ===	(mou)							•
						-	193 41	.det > 1).						
						-	191 001	3 20 -				•			
						-	1102 ~	TALS							
				ļa.	•	-	X nuar							."	
					•,	- 1	tamina			s					•.
G. LIST SUBSTA	NC25	of Greatest Con-		WHICH 2 FORM		_		in 4040	•0410	ar	der of hazard)				
1_5	L SSTA	MCI:		merk 'X	7)	(34	XICITY		 <u></u> _	25	MUMBER	5.4		UNT	6. UNIT
			410		200 HIGH			HONG							
creososte	cons	tituents:							• .						
fluorene				X	х				un	kr	nown	uı	nkı	nown	
phenanthre	ne			х	x				85	01	L8	, ui	nkı	nown	
fluoranthe	ne			Х	x				20	64	140	uı	nk	nown	
pyrene				X	х				12	90	000	uı	akı	nown	
acenaphthe	ne			x	x	<u> </u>			un	kr	own	ur	nkı	nown	
napthalene				X	<u> </u>	-			91	20)3	uı	nkı	nown	
benzo(a)an	thra	cene		X	X				un	kr	nown	uı	nk	nown	
FIELD EVALU.		HAZARO DESCR	PTIC		II. HAZARI ece en 'X' u				e that	'th	e-listed haz	erd exis	(3.	Describe	the .
XX A. HUMAN									:	_					· · · · · · · · · · · · · · · · · · ·
		ists for hum d adjacent t							d sc	i]	l off si	te lo	ca	ted acı	ross
			. 1						٠.						

VIII. HAZARD DESCRIPTION (continued)	
XX 3- NOM-HORKER INJURY/EXPOSURE	
Possibility exists for contact with off-site contaminated so side of Lufkin Ave. across from the site.	oil located on the south
	42
	•
C WORKER INJURY/EXPOSURE	
None observed	•
C CONTAMINATION OF WATER SUPPLY	
CONTAMINATION OF WATER SUPPLY	·
None observed	•
	•
	•
CONTAMINATION OF FOOG CHAIN	and the second s
None observed	
	•
	· ·
XXF. CONTAMNATION OF GROUNG WATER	The state of the s
Possibility exists since groundwater is approximately 50-75 and drainage ditch traversing the site appeared to be conta constituents during the inspection.	feet below the surface minated with creosote
XX G. CONTAMINATION OF SURFACE WATER	
Drainage ditch traversing site visually appeared to be cont constituents. Surface water in ditch had an oily sheen.	aminated with creosote

	VIII. HAZARD DESCRIPTION (continued)
H. CAMAGE	to floral fauna.
None obse	erved
I. FISH XILL	
· -	
None obse	erved
t it is	
1. CONTAMIN	ia tion of air
• :	
None obse	erved
XX X. NOTICEA	BLE GROAS
Creosote	odors present in the drainage ditch traversing the site.
XX L. CONTAMI	NOTION OF SOIL
	And the state of t
	ted soil present in the drainage ditch at the east side of the site
una 111 01	
M. PROPERT	Y SAMAGE
None obse	ervea
· .	

Continued From Page 6				<u> </u>	
Section 1997	· VIII. HAZARE	DESCRIPTION	(continued)		
N. FIRE OR EXPLOSION		-	•		
None observed				:	
, Mone observed	$\mathcal{E}_{-\infty}$	·. ·.			
			•		
			•	•	•
	•				
				· · · · · · · · · · · · · · · · · · ·	
QQ O. SPILLS/LEAKING CONT.	AIMERS/RUNGFF/STANGING L	ridaid.	•		
Runoff of an oil	y sheen observed in	drainage (ditch travers	sing the	site.
		•		· · ·	
	:				
•					N. A.
	•				•
P. SEWER, STORM CRAIN A	408LEHS			 	
_	•				
None observed					
		•			
				•	
	•				
	• .			•	
•					
XX G. EROSION PROBLEMS	· · · · · · · · · · · · · · · · · · ·	- <u></u>			
	the authorsh		to dominada .	وكر المستلفة	- the cost side
Erosion observed of the site.	along the culvert	(part or the	ne drainage o	alten) or	the east side
of the site.					
		•			
				<u> </u>	
A. INAGEQUATE SECURITY					***************************************
		•			
None observed					
	. ·	•			
					·. '
		•		•	
					•
					
S. INCOMPATIBLE WASTES					
Warra shookyod					
None observed				•	
			•		
•	•				

						
	VIII. HA	ZARO DE	SCRIPTION /contin	।पक्द)		
T, MIGHIGHT GUMPING						•
None observed		'				
	;					
	1	1.			•	
	-					
	ŀ					
		•			•	
UL OTHER (*Gentlett					· · · · · · · · · · · · · · · · · · ·	
	!				•	•
	-	• .			•	٠.
None observed						
	. 1				•A	1.
					ý.	•
· 1						•
	;• 			•	•	
					•	
			•		*	
	. 1					
	. 1	•				
			•		•	V
į	1	•				
	(
	!		,			
•						
	IX POPULAT	פאונ אסר	CTLY AFFECTED	STIL YE		
ALCCATION OF POPULATION	g. approx. Of People aft		C. APPROX. NO. O AFFECTED WI UNIT ARE	THIN	G. APPROX. 40. OF BUILDINGS AFFECTED	E. DISTANCE TO SITE (specify units)
I.IN RESIDENTIAL AREAS	20,000		20,000		6,670	l mile
IN COMMERCIAL.	6,930	· 1	6,930		693	4 miles
IN PUBLICLY TRAVELLED AREAS.	35.000	1	35,000	1;	_	l mile
MISUIC USE LATAS (pares, sepondo, etc.)	9,000	:	9,000		20	4 miles
- 1	X		O HYDROLOGICAL			
55 to 75 feet		, south	-3w easterly		iblic, domesti	
G. POTENTIAL YIELD OF AQUIFER	E. DISTA	NCE TO DR	HKING HATER SUP	FLY F. 31	RECTION TO CRINKI	IG WATER SUPPLY
200 - 500 gpm	1 1.	to l.	6 miles	sou	th to southwe	est, east
G. TYPE OF CHINKING WATER SUPE	L COMMUNITY (100	eity (pwn):				
CIS CONNECTIONS	> 15 CONNECTION	45 -	estock 37-	43-401	4B, 4C, 4D,	
	DOMES	//	CDCCK. JI-		,,, .	1

EPA Fam 72070-3 (10-79)

M. LIST ALL OR	JOW RETAN DNIXM	X WATER AND HYDROLD		(continued)		
1. *< LL	2. JEPTN (29edity unit)	1	. LOCATION population/ buil	idingaj	NGM-COM- HUNITY (Bark 'X')	(Stand 'X')
None known						
	·			•		
· 					·	
	nt Creek of	2 sewers	XX 1. ST#EAD	ERJ VIR LE		
Hurricane (THE CAMESTACIES OF		(aposity):		
		TON OF RECEIVING WATERS				·
	er Basin, Se			e er - v - u a	ca	
		contact recreation, p	ropagation	of fish and wildi	Life and	
dome	estic raw wa			• .		
LOCATION OF S	ITE IS IN:	XI. SOIL AND VEC	AU RUITATI	[A		
A KNOWN Possil		E. KARST ZONE	☐ c 1000 .	YEAR FLOOD PLAIN	G. WETLAND	١.
S A REGUI	LATED FLOODWAY	F. CRITICAL HABITAT	C. REC	HARGE ZOME OR SOLE SOUR	CZ AQUIFER	
		XII. TYPE OF GEOLOGICA				
Mark 'T' to man	gate the type(s) or	geological material observed an	d specify when	e decousery, the component	parts.	
A. GVERBU	ROEN X	8. SEDROCK (specify below)	, [C- QTHER (A)	etty belawj	·
1. SAMG	.					
X 2. GLAY						
3. GRAVEL					************************************	
		XIII. SOIL PES	MEABILITY			
Permeabili A. unknow	* 4	10 ⁻⁵ cm/sec 8. very high (190,000 m XX 5. LOW (.1. to .001 and sec		C_ HIGH (1000 to 10 cm		4.)
G. RECHARGE A		DMMENTS:				
H. SISCHARGE A	REA	<u> </u>		ges at the intermit	ttent cre	ek
1. SLOPE				h ''' - ' ' ' ' - ' - ' - ' - ' - ' - ' -		
1. ESTIMATES		PECIFY DIRECTION OF SLOPE, C		LOPE. ETC.		
0-3		ightly towards southw	est			
J. OTHER GEOL				C CO	11 and	1
	Rosenwall br 40 percent o	own fine sandy loam, ther soils.	CONSISTS	of 60 percent kose	NWall and	I
See Attach	ment A					

				-			•	•
ntinued िन्त्रत टैंट	on!		VIII - 0.00					
ist all applicable	e seemila ite	מונף פנו שנ או	and provide the rela	T INFORMATION			<u> </u>	
				G. CATE	S. EXPIRATION		CSMPU.	
A. PERMIT CARCIA, SIMONE		DAIDEEL E YDANDA	C. PERMIT NUMBER		3745	7 €3	2. NG	3. UM
one						1		
							1	
							}	
		XV. 24	ST REGULATORY	OR ENFORCEMENT	CTIONS			
a	ind was d	lated Sept	ember 29, 19	W. Moritz was : 82 (TWC Distric	issued to Luf ct 6 office).	kin Cr No d	eosoti etails	ng
a	ind was d	lated Sept	tter from C. tember 29, 19	82 (TWC Distric	issued to Luf	kin Cr No d	eosoti etails	ng
a	ind was d	lated Sept	ember 29, 19	82 (TWC Distric	issued to Luf ct 6 office).	kin Cr No d	eosoti etails	ng
a	ind was d	lated Sept	ember 29, 19	82 (TWC Distric	issued to Luf ct 6 office).	kin Cr No d	eosoti etails	ng
a	ind was d	lated Sept	ember 29, 19	82 (TWC Distric	issued to Luf ct 6 office).	kin Cr No d	eosoti etails	ng
a	ind was d	lated Sept	ember 29, 19	82 (TWC Distric	issued to Luf ct 6 office).	kin Cr No d	eosoti etails	ng ·
a	ind was d	lated Sept	ember 29, 19	82 (TWC Distric	issued to Luf ct 6 office).	kin Cr No d	eosoti etails	ng
a	ind was d	lated Sept	ember 29, 19	82 (TWC Distric	issued to Luf ct 6 office).	kin Cr No d	eosoti etails	ng
a	ind was d	lated Sept	ember 29, 19	82 (TWC Distric	issued to Luf ct 6 office).	kin Cr No d	eosoti etails	ng
a	ind was d	lated Sept	ember 29, 19	82 (TWC Distric	issued to Luf ct 6 office).	kin Cr No d	eosoti etails	ng
a	ind was d	lated Sept	ember 29, 19	82 (TWC Distric	issued to Luf	kin Cr No d	etails	ng
a o	and was on the er	lated Septiforcement	tember 29, 19	82 (TWC Distric	ct 6 office).	No d	etails	
a o	on the en	lated Sep	tember 29, 19 t letter are	82 (TWC District available.	ct 6 office).	No d	etails	

ATTACHMENT A:

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT SUPPLEMENT SHEET

Instruction - This sheet is provided to give additional information in explanation of a question on the form T2070-3.

Corresponding number on form

Additional Remark and/or Explanation

VI-D

A surface impoundment was once used to contain creosote wastewater blowdown. The impoundment was closed in 1973 or 1974 without TDWR participation or oversight.

XIII.J.

The Yegua Formation, the outcropping strata in the site, acts as the major shallow aquifer for the region (Lufkin). It is the uppermost formation of the Claiborne Group and is composed of thin-bedded sand, silt and clay with a thickness ranging from 150 to 400 feet near Lufkin (see Figure 1, cross-section A-A in Attachment B). The Yegua Formation is underlain by the Cook Mountain, Sparta, Reklan, and Carrizo Formations in descending order with a total thickness of 1100 to 1200 feet. The Wilcox Group is overlain by Carrizo sand (120 feet thick), followed by the Midway Group of other Eocene-Tertiary age.

There are several minor faults in Lufkin and the vicinity, which is significant with respect to the occurrence and movement of groundwater. The outcrop pattern trends nearly east-west with the dip towards south, and southeast at a rate of 150 feet per mile.

ATTACHMENT B


	Stratigraphic and Hydrogeologic Information
<u>X</u>	Site Inspection Supplimental Report(s)
	Groundwater Monitoring System Supplimental Form
	Residential Well Sampling Information
	Boring Logs and/or Monitoring Well construction and design


Table . . - Stratisms of Units and Their Water Bearing Properties in Angelina agencycogdoches Counties

Stratigraphic Unit	Approximate Range in Thickness (feet)	Approximate Thickness at Macogdoches (feet)	Approximate Thickness at Lufkin (feet)	Composition	General Water-Bearing Properties
Alluvium	c- 30	. 0	Э	Sand, silt, and clay, with some gravel.	Locally yields small quantities of fresh water to videly scattered shallow dug wells.
Cataboula Formation	<u>2</u> /	. 0	o	Sand with some clay.	Yields no water to wells.
Jackson Group ✓	9-1,600	0	o	Mostaly clay and silt.	Yields small quantities of fresh to brackish water.
Yegus Formation	0-1,050	0	150-400	Mostly thin-bedded sand, silt, and clay.	Yields small to moderate quantities of fresh to brackiah water.
Cook Mountain Formation	0-500	o	410	Mostly clay.	Yields small quantities of fresh to brackish water in outcrop area.
Sperta Send	o-29o	o- 7a	500	Interbedded sand and clay.	Yields small to moderate quantities of fresh water in and near outcrop area.
Weches Formation	9- 249	140	150	Mostly clay.	Yields small quantities of fresh to brackish water in outcrop area.
Queen City Jend	0-130	60	50	Interbedded sand and clay. Sands feather out to south and east.	Yields small quantities of fresh water, mostly in outcrop area.
Reklaw Formation	0-290	200	250	Clay and siit, typically having a basal sand.	Yields small quantities of fresh to brackish water.
Carrizo Send	0-170	90	120	Massive sand.	Yields moderate to large quantities of fresh water.
Wilcox Group	950-3,300	2,500	<u>2</u> /	Interbedded send, silt, and clay.	Yields small to moderate quantities of fresh water.
Midway Group	2/	2/	<u>2</u> /	Mostly clay.	Yields no water to wells .

Source: TOWR Report 110, March 1970

^{1/} Includes Whitsett Formation of Eocene or Oligocene age and Manning, Wellborn, and Caddell Formations of Eocene age.





SURFACE IMP SHOMENTS SITE INSPECTION REPORT

INSTRUCTION
Answer and Explain
as Necessary.

(Supplemental Report)	as Necessary.
TO TYPE OF IMPOUNDMENT	<u> </u>
Storage earthern surface impoundment - closed in 1973 or 1974	
ZI-STABILITY/CONDITION OF EMBANKMENTS	
Not applicable (N/A) - embankments were pushed inward to fill the	ne impoundment
3. EVICENCE OF SITE INSTABILITY (Erosion, Settling, Sink Holes, etc.)	
TYES THO N/A 4. EVICENCE OF DISPOSAL OF IGNITABLE OR REACTIVE WASTE	
i ves one N/A	
3. ONLY COMPATIBLE WASTES ARE STORED OR DISPOSED OF IN THE IMPOUNDMENT	
[] YES [] NO N/A	A DOMESTIC OF THE STATE OF THE
6. RECORDS CHECKED FOR CONTENTS AND LOCATION OF EACH SURFACE IMPOUNDMENT	
7: IMPOUNDMENT HAS LINER SYSTEM TO INTEGRITY OF LINER SYSTEM	CHECKED
TYES XX NO	
78. FINDINGS	
8. SOIL STRUCTURE AND SUBSTRUCTURE	
clay soils	
S. MONITORING WELLS	
TO TENGTH, MOTH, AND GEPTH	
LENGTH 80 feet winth 150 feet DEPTH 28 inches	
11. CALCULATED VOLUMETRIC CAPACITY	
1000 cubic yards	_
12 PERCENT OF CAPACITY REMAINING	
N/A IL ESTIMATE FREEBOARD	
N/A	
14. SOCIOS GEPOSITION	
XX YES NO NO TENDENCING DISPOSAL METHOD	
N/A	
16. OTHER EQUIPMENT	
	•
	,
	•

MANIFESTS FOR PENTACHLOROPHENOL SLUDGE

EXHIBIT A

	1. MANIFEST NUMBER
-	Generator I.D. No. 6-9798
į	Sequence No.

STATE OF LOUISIANA DEPARTMENT OF NATURAL RESOURCES HAZARDOUS WASTE MANAGEMENT P. O. BOX 44396 BATON ROUGE, LOUISIANA 70804

For Dept. Use
Index #
Date

HM	SHIPPING DESCRIPTION HAZARDOUS WASTE)	HAZARD CLASS	WASTE NUMBER	WEIGHT (TONS)	QTY.	TVOC
				110.0 (1010)		TYPE
		ORM-E	9798-01	10	/	BULK
	LIQUID, NIOS,	<u> </u>				TANKE
1	(PENTACHED ROPHANOL)	· · · · · · · · · · · · · · · · · · ·				
						<u> </u>
3.	GENERATOR INFORMATION:	Identification Numbe	- G-9799	Telephone: (409) 6	24-507	5
.	NAME OF COMPANY: LUF			receptions: (401)	<u>g , </u>	
		DY LUFKIN, T		ZIP: 75-9	01	 -
•	SHIPPING LOCATION: /41					 .
4	CERTIFICATION: This is to ce				ckaged, marl	ked and
	labeled, and are in proper condi-	tion for transportation	according to the applic	cable regulations of the Department	artment of Ti	ranspor-
	tation, and the Louisiana Departr	nent of Natural Resour	ces. EPA+ TXO	00 806 3661		
			· .	1-20	- 02	
	Generator Sig	Mer.		a 6-24	<u> </u>	
		•				
4.	TRANSPORTER INFORMATIO	N: Identification Num	iber: 1-278-14	Telephone -800-	231-92	25
	NAME OF COMPANY:	BFI	DATE OF PICK UP	: b-24-83 TIN	1E: 18:00	Am
	CERTIFICATION: This is to c	ertify that the above-n				
	Øst of the transporter's knowled	ge, his portion of the m	nanifest is accurately and	d correctly filled out.		
1	4 th way to	VA			•	
	Transporter Sign	1009931332	\$27			,
	CERTIFICATION: This is to ce	rtify that the above-nar	ned materials were deliv	ered without incident to the	disposer at t	he date
	and time below.	•		•		
	Handle Market	4		Y 6-24-83 TIM	- 19:00	0
	San Mores Cut	ature	DATE OF DELIVER	Y <u>567 85</u> TIM	ME: /cx - 74	250
				· · · · · · · · · · · · · · · · · · ·		
5.	DISPOSER INFORMATION: Ide	entification Number:	D-539	Telephone: (318) 5	27-685	>
	NAME OF COMPANY: BFI	- CECOS IN	TL			
	LOCATION WHERE SHIPMENT	RECEIVED: WILL	DW SPRINGS RI	O. NORTH OF SULP	HUR, LA	
	CERTIFICATION: This is to ce	rtify acceptance of th	e hazardous waste, tha	the waste has been or wi	Il be dispose	d of in
	accordance with Department of	•				
	accurately and correctly filled out				·	
		10 11.11		6-14	-12	
	() (e Kary		0 01	0	
	Disposer Signa	ture .	·	Date		
6.	EMERGENCY INFORMATION:					
•	Immediate Response Information	In case of acc	cident or spill.	call Louisiana Depa	artment o	f
	Public Safety	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	Telephone: <u>(504) 92</u>	5 - 6595	
	Special Handling Instructions:	· · · · · · · · · · · · · · · · · · ·				
			····		 	
•	Comments:		· · · · · · · · · · · · · · · · · · ·			







Ticket No 00552026

TEXAS WASTE SHIPPING—CONTROL TICKET (Please Type or Print Clearly)

(Satisfies TDWR, TDH and U.S. EPA requirements for hazardous or class (Lwaste manifest)

PART I: To be ço		_			ructions)	e ku i ku		TDWR/TDH I	Registration	UR No. 3/	83 2
Company Name	CUFKIN O				5901						00806	
	PO, BOX 128 ich Shipment Orig		7167 1	<u>~ ~</u>	- 10 1				EPA Gen. #	I KU	SARAME	001
	LUFKIN /		Luft	עמוצ	7X		•		Emergency Pt	none A/C	409) 634	-50 2
DESTINATION: Primary TSD Faci	lity Nama RF	a- CE	cas J	בז אב			: •		TDWR/TDH	Permit No.	/A	II
	POLBOX 5							6	EPA TSD Fac.	# [40]	0056V R	256
	Address WILL				_						27-685	7
Alternate TSD Fa	cility Name	· · · · · · · · · · · · · · · · · · ·		<u>.</u>		<u>-</u> -			TDWR/TDH,	Permit No.	Шİ	
Business Address	······································		<u> </u>	·				<u> </u>		·	7 1 1 1 1	_
Destination (Site)	Address	•				···	+	 .	EPA TSD Fac. Phone A/C	# [
1. TEXAS WASTE CODE	2: QUANTITY	UNITS*		WASTE		4. C	OT CLASS	5.	(a) DOT DESCR NUMBER	IPTION; (LOF CONT)
15/230	2500	1034	NA	91	8 9	<u>'</u>	Z	HA	tzaklou:	s was	7F, LIQ	UIP
1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	7.11	1234		<u> </u>	ļ	1	-	N	10,5.		.201	
		1234		 	 - -	╀	<u>. </u>	-	OPNITACHLON	12 Od CA	~	
 	<u> </u>	1234	-		1 1			<u> </u>	ICH -OL	=UI: NEIU		
2.19		1234			 	1~		<u> </u>	1 BW	K 74	NKER	
	٠.	1 2 3 4		1 12 1	1 1				1 * * 145		1 8 8 10 10 10 10 10 10 10 10 10 10 10 10 10	
		1 2 3 4	į	i i.			77	e. 11	West to		·	7 5
This is to certify described, packag transportation accand TDH.		abeled and a	re in pro	per cor	ndition f	or.	r	Ax	Date of Date o	Shipment Market Authorized A	line:	·
PART II: To be Carrier Name Business Address Phone Number A I certify (or declare received by	BFI Fart /C 1-801 are) that the mate	C-373	y /) / J	s descri	bed abo	<u>.</u> 	struct	:		24-y	019151913 1	1 4 7 3 8 19
PART III: To be Facilit TSD Facility Nar Phone Number Site Address TSD Facility Own	y Owner/Operato	or (see reve	rse side	BFI: Y CALCA WILLO WESTL P.O. BO	Kristabli Vaste s Isleu fi W spri Ake, La Ox sala	SYSTE NCILI NGS	MS TY RD.	E	TDWR/TDH F		P3	
I certify (or decla		als in the qu		H V #	HARLE LAD 00 d in Pari	0618 :	7066 256 ——	D6 	Signature	7	La	
are received by me	•	`.:		•					Signature of	Authorized A	en e	


ATTACHMENT C

None Groundwater Monitoring Data

None Report(s) from Previous Site Investigation(s)

ATTACHMENT D

- ___ Site Safety and Work Plan
- χ Site sketch \cdot
- _X Laboratory data
- X Chain-of-Custody form(s)
- X Topographic map
- X Floodplain map
- <u>X</u> Photographs



ES ENGINEERING-SCIENCE

RESEARCH AND DEVELOPMENT LABORATORY • 600 BANCROFT WAY • BERKELEY, CALIFORNIA 94710 • 415/841-7353

Priority Pollutant Analysis
Creosote Constituents + Pentachlorophenol- EPA 8270
+ its degradation products

Date Received 7/23/86
Date Reported 8/20/86

P.O. No. Job No. ZB104 Page 1 OF 1

For: ES-Austin/Texas Water Commission

Address:

Attn: Barry Hubbard

Source of Sample:

Lab No:

TX13765-1

861817

Date Collected:

7/22/86

Time Collected:

1552

Acenaphythylene 5 5 5 Acenaphthene 3 70 Fluorene 3 115 Phenanthrene 10 124 Anthracene 3 29 Fluoranthene 3.5 ND Pyrene 3 99 Chrysene 4 31 Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 4-Chloro-3-methylphenol 5 ND 4-Chloro-3-methylphenol 5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dimitrophenol 70 ND	Compound	Detection Limits	ANALYTICAL RESULTS
Acenaphthylene 5 5 5 Acenaphthene 3 70 Fluorene 3 115 Phenanthrene 10 124 Anthracene 3 29 Fluoranthene 3.5 ND Pyrene 3 99 Chrysene 4 31 Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND		mg/kg	mg/kg
Acenaphthene 3 70 Fluorene 3 115 Phenanthrene 10 124 Anthracene 3 29 Fluoranthene 3.5 ND Pyrene 3 99 Chrysene 4 31 Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Naphthalene	2.5	31
Fluorene 3 115 Phenanthrene 10 124 Anthracene 3 29 Fluoranthene 3.5 ND Pyrene 3 99 Chrysene 4 31 Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 5 ND 2,4-Dinitrophenol 70 ND	Acenaphythylene	5	5
Phenanthrene 10 124 Anthracene 3 29 Fluoranthene 3.5 ND Pyrene 3 99 Chrysene 4 31 Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 4.5 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Acenaphthene	3	70
Anthracene 3 29 Fluoranthene 3.5 ND Pyrene 3 99 Chrysene 4 31 Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 4.5 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Fluorene	3	115
Fluoranthene 3.5 ND Pyrene 3 99 Chrysene 4 31 Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 4.5 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Phenanthrene	10	124
Pyrene 3 99 Chrysene 4 31 Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Anthracene	3	29
Chrysene 4 31 Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 4.5 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Fluoranthene	3.5	ND
Benzo(a)anthracene 15 42 Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Pyrene	3	99
Benzo(b)fluoranthene 10 11 Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 4.5 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Chrysene	4	31
Benzo(a)pyrene 4 5 Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Benzo(a)anthracene	15	42
Indeno(1,2,3-c,d)pyrene 5 8 Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Benzo(b)fluoranthene	10	11
Dibenzo(a,h)anthracene 4 ND 2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Benzo(a)pyrene	4	5
2-Chlorophenol 5 ND Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dimitrophenol 70 ND	Indeno(1,2,3-c,d)pyrene	5	8
Phenol 2.5 ND 2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Dibenzo(a,h)anthracene	4	ND
2,4-Dimethylphenol 4.5 ND 2,4,5-Trichlorophenol 10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	2-Chlorophenol	5	ND
2,4,5-Trichlorophenol :10 ND 2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	Phenol	2.5	ND
2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	2,4-Dimethylphenol	4.5	ND
2,4,6-Trichlorophenol 4.5 ND 4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	2,4,5-Trichlorophenol	<u>-</u> 10	ND
4-Chloro-3-methylphenol 5 ND 2,4-Dinitrophenol 70 ND	2,4,6-Trichlorophenol	4.5	ND
2,4-Dinitrophenol 70 ND			ND
		. 70	ND
	Pentachlorophenol	5	ND

Mulu Supervisor

ES ENGINEERING-SCIENCE

RESEARCH AND DEVELOPMENT LABORATORY • 600 BANCROFT WAY • BERKELEY, CALIFORNIA 94710 • 415/841-7353

Priority Pollutant Analysis
Creosote Constituents + Pentachlorophenol- EPA 8270

+ its degradation products

Date Received 7/23/86
Date Reported 8/20/86

P.O. No.
Job No. ZB104
Page 1 OF 1

For: ES-Austin/Texas Water Commission

Address:

Attn: Barry Hubbard

Source of Sample:

Lab No:

TX13765-2 861818

7/22/86

Date Collected: Time Collected:

2,4-Dinitrophenol

Pentachlorophenol

1607

Compound Detection ANALYTICAL RESULTS Limits mg/kg mg/kg Naphthalene 1 82 Acenaphythylene 2 3 Acenaphthene 1.2 125 Fluorene 1.2 223 Phenanthrene 214 Anthracene 1.2 44 Fluoranthene 1.4 165 Pyrene 1.2 142 Chrysene 1.6 34 Benzo(a)anthracene 6 49 Benzo(b) fluoranthene 4 19 Benzo(a)pyrene 1.6 6 Indeno(1,2,3-c,d)pyrene 2 ND Dibenzo(a,h)anthracene 1.6 ND 2-Chlorophenol 2 ND Phenol 1 5 2,4-Dimethylphenol 1.8 ND 2,4,5-Trichlorophenol ND 2,4,6-Trichlorophenol 1.8 ND 4-Chloro-3-methylphenol 2 ND

28

2

Laboratory Supervisor

ND

ND

ES ENGINEERING-SCIENCE

RESEARCH AND DEVELOPMENT LABORATORY • 600 BANCROFT WAY • BERKELEY, CALIFORNIA 94710 • 415/841-7353

Priority Pollutant Analysis
Creosote Constituents + Pentachlorophenol- EPA 8270
+ its degradation products

Date Received 7/23/86 Date Reported 8/20/86

P.O. No.
Job No. ZB104
Page 1 OF 1

For: ES-Austin/Texas Water Commission

Address:

Attn: Barry Hubbard

Source of Sample:

Lab No:

TX13765-3

861819

Date Collected:

Time Collected:

7/22/86

1617

Compound	Detection	ANALYTICAL RESULTS
	Limits	
	mg/kg	mg/kg
Naphthalene	1	ND
Acenaphythylene	2	ND
Acenaphthene	1.2	4
Fluorene	1.2	6 .
Phenanthrene	. 4	11
Anthracene	1.2	18
Fluoranthene	1.4	40
Pyrene	1.2	72
Chrysene	1.6	26
Benzo(a)anthracene	6	26
Benzo(b)fluoranthene	4	18
Benzo(a)pyrene	1.6	4
Indeno(1,2,3-c,d)pyrene	2	4
Dibenzo(a,h)anthracene	1.6	ND
2-Chlorophenol	2	ND
Phenol	1	ND
2,4-Dimethylphenol	1.8	ND
2,4,5-Trichlorophenol	4	ND
2,4,6-Trichlorophenol	1.8	ND
4-Chloro-3-methylphenol	2	ND
2,4-Dinitrophenol	28	ND
Pentachlorophenol	2	ND

Man Sulfor Laboratory Supervisor

ENGINEERING-SCIENCE

RESEARCH AND DEVELOPMENT LABORATORY • 600 BANCROFT WAY • BERKELEY, CALIFORNIA 94710 • 415/841-7353

Priority Pollutant Analysis Creosote Constituents + Pentachlorophenol- EPA 8270 + its degradation products

Date Received 7/23/86 Date Reported 8/20/86 P.O. No. Job No. ZB104 Page 1 OF 1

For: ES-Austin/Texas Water Commission

Address:

Attn: Barry Hubbard

Source of Sample:

Lab No:

TX13765-4

861820

Date Collected:

7/22/86

Time Collected:

1644

Compound	Detection	ANALYTICAL RESULTS
	Limits	•
	mg/kg	mg/kg
Naphthalene	.05	ND
Acenaphythylene	.1	ND
Acenaphthene	.06	ND .
Fluorene	06	ND
Phenanthrene	.2	ND
Anthracene	.06	ND
Fluoranthene	.07	.09
Pyrene	.06	.19
Chrysene	.08	.08
Benzo(a)anthracene	.3	ND
Benzo(b)fluoranthene	.2	ND
Benzo(a)pyrene	.08	ND
Indeno(1,2,3-c,d)pyrene	.1	ND
Dibenzo(a,h)anthracene	.08	ND
2-Chlorophenol	.01	ND
Phenol	.05	ND .
2,4-Dimethylphenol	.09	ND
2,4,5-Trichlorophenol	.2	ND
2,4,6-Trichlorophenol	.09	ND
4-Chloro-3-methylphenol	.1	ND
2,4-Dinitrophenol	1.4	ND
Pentachlorophenol	.1	ND

CHAIN OF CUSTODY RECORD

						CHAIN U	r Cus	OIC	זטי	KE	CORL	J	-
	PROJECT 56360			NO. OF CONTAINERS	The state of the s								
	56360.00 TWC (ST. SAMPLERS (Signatures) Bang Rubbard												REMARKS REMARKS
	STA. NO.	DATE	[_	1	GRAB	STATION LOCATION					//		possible high contamination in sumples To 13765-2 through 4
TX 1376	5-1	7/22/	3:52 4:07	50	X	Background soil		V	4				for creosote constituents see
		- 1	11:45			3				_		ļ	attached list.
TX 13768	-2	7/22/ 86	434	51	N	Brickgraind Sediment		_				<u> </u>	1818
		1		1			ļ	ļ		_	<u> </u>		for all methods of analysis, and
TX 1374	5-3	86	7:25	150	X	495 Downstream Sediment		~	4		_		extraction see the attached methods 1819
			<u></u>	<u></u>				ļ					from the QA/QC plan in the
TX137	5-4	7/22/	4:44	Ĺ	X	Pond subsurface		1	1				Plane Preliminary Assessment/Site 1821
	ļ		<u> </u>					<u> </u>					Inspection Manual.
			<u> </u>							\perp			for pentuchlorophenol look also for
													the 10-20 et poules for degradation des-
		<u> </u>											ducts Peaks must be greater than 1000
	Relinquis				7/22	Date/Time Received by: (Signature) 186 7:00 Federal Express Date/Time Received by: (Signature)		Reli	nquish	ed by	: (Signa	ture)	ducts. Peaks must be greater than loss Date/Time Received by: (Signature) of the internal standard.
	Relinquis	hed by:	(Signati	ure)		Date/Time Received by: (Signature)		Reli	nquish	ed by	: (Signa	ture)	Date/Time Received by: (Signature)
ż	Relinquis	hed by:	(Signati	ure)		Date/Time Received for lab. by: (Signat	țure)	7/2	Dote 23	/Time	Rem 30 B	narks	COLD, INACT LE LABELED AS FOLLOWS:
J_i						/ -					-	137	65-1 TIME 3:52 NOT 4207

PROBLEM RESOLVED FROM

-2 ", 4:07 " 4:17

PHONE CONVERSATION WI LISA ARCENTAUX

ON 7/25 SHEET TIMES CHANGED BY JOE M. PHONE CONVERSATION W/ DAVID WILKES 7/23

UNITED DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY NACOGDOCHES IN MI 42'30" 1 33 (3) 103 3469 20' SCALE 1:24000 1000 1000 5000 8W/4 LUFKIN 15' QUADRANGLE 7000 FEET : NILOMETER N3115-W9437.5/7.5 1949 **CONTOUR INTERVAL 10 FEET** PHOTOREVISED 1980 DOTTED LINES REPRESENT S-FOOT CONTOURS NATIONAL GEODETIC VENTICAL DATUM OF 1929

DMA 7046 ! SW-SERIES V882



TO MAP

500-Year Flood Boundary	-
100 %	ZONE B
100-Year Flood Boundary	CONE ALE PER
Zone Designations*	ZONE 345
100-Year Flood Boundary	
500-Year Flood Boundary	ZONE B
Base Flood Elevation Line With Elevation In Feet**	513
Base Flood Elevation in Feet Where Uniform Within Zone**	(EL 987)
Elevation Reference Mark	RM7 _X
Zone D Boundary————	
River Mile	•M1.5
** Referenced to the National Geodet	tic Vertical Datum of 1929

Zone D B	Soundary
River Mil	e •M1.5
**Refere	nced to the National Geodetic Vertical Datum of 1929
*EXP	LANATION OF ZONE DESIGNATIONS
ZONE	EXPLANATION
. •	Areas of 100-year flood; base flood elevations and flood hazard factors not determined.
AO	Areas of 100-year shallow flooding where depth are between one (1) and three (3) feet; average depth of inundation are shown, but no flood hazard factor are determined.
AH	Areas of 100-year shallow flooding where depth are between one (1) and three (3) feet; base flood elevations are shown, but no flood hazard factor are determined.
A1-A30	Areas of 100-year flood; base flood elevations and flood hazard factors determined.
A99	Areas of 100-year flood to be protected by flood protection system under construction; base flood elevations and flood hazard factors not determined
B	Areas between limits of the 100-year flood and 500 year flood; or certain areas subject to 100-year flood ing with average depths less than one (1) foot or when the contributing drainage area is less than one square mile; or areas protected by levees from the base flood (Medium shading)
C	Areas of minimal flooding. (No shading)
D	Areas of undetermined, but possible, flood hazards
V .	Areas of 100-year coastal flood with velocity (wave action); base flood elevations and flood hazard factor not determined.
V1-V30	Areas of 100-year coastal flood with velocity (wave action); base flood elevations and flood hazard factors determined.

NOTES TO USER

Certain areas not in the special flood hazard areas (zones A and V) may be protected by flood control structures.

This map is for flood insurance purposes only; it does not necessarily show all areas subject to flooding in the community or all planimetric features outside special flood hazard areas.

For adjoining map panels, see separately printed Index To Map Panels.

INITIAL IDENTIFICATION: FEBRUARY 22, 1974

NATIONAL FLOOD INSURANCE PROGRAM

FIRM

FLOOD INSURANCE RATE MAP

CITY OF LUFKIN, TEXAS ANGELINA COUNTY

PANEL 10 OF 10


COMMUNITY-PANEL NUMBER 480009 0010 B

EFFECTIVE DATE:

JUNE 1, 1982

Federal Emergency Management Agency





Lisa Arceneaux / Barry Hubbard

Date / Time / Direction

7/22/86 3:06 SE


Comments: Old storage tank area.

Note the blackened soil to

the right of the concrete pad.







Lisa Arceneaux / Barry Hubbard

Date / Time / Direction

7/22/86 3:08 NW

Comments: Boiler left on site.

after the facility was closed.





Photographer / Witness

Lisa Arceneau / Barry Hubbard

Date / Time / Direction

7/22/86 3:17 5

Comments: Abandoned Surface

impoundment, filled with soil.

(Foreground) Barn in background.











Photographer / Witness

Date / Time / Direction

7/22/86 3:25 5

road split at the seam. Blackened soil visible in the 3-6 inches of soil below the surface.

Photographer / Witness

Lisa Arceneaux / Barry Hubbard

Date / Time / Direction

7/22/86 3:27 SE

Culuent.

5

Photographer / Witness

LISA Arceneaux / Barry Hubbard

Date / Time / Direction

7/22/86 3:37 NW

Comments: Four 120 foot treatment

cylinders Stored at the site.





Photographer / Witness

Lisa Arceneaux / Barry Hubbard Date / Time / Direction

7/20186 3:52 W

Comments: Background soil Danny

Vines split soil samples.





Photographer / Witness

Lisa Arceneaux / Barry Hubbard

Date / Time / Direction

7/20/86 4:07 E


Comments: Upstream sediment

(TX 13765-2).

IN Chrainage ditch Inside Mr

Vines property line.





Lisa Arconeaux /Barry Hubbard

Date / Time / Direction

7/22/86 4:17 N

Comments: Danustream Sediment


samplex Black stains on the

ground Agrass.









Photographer / Witness


Lisa Arceneaux / Barry Hubbard

Date / Time / Direction

7/20186 4:20 N

case ditch near the location





Lisa Arceneaux / Barry Hubbard

Date / Time / Direction

7/22/86 4:40 NF

Comments: Old surface impoundment

location. Augering for Sample







Photographer / Witness

Lisa Arceneaux / Parry Hubbard

Date / Time / Direction

7/22/86 4:44 NE

Comments: Subsurface soil sample

from the surface impoundment taken

at 2 feet down. (Tx 13765-4).

TWC SITE INSPECTION COMMENTS LUFKIN CREOSOTING COMPANY LUFKIN, TEXAS TX 13765

DOCUMENTATION OF SITE ACTIVITIES AND SITE HISTORY

On July 22, 1986 a TWC site inspection was conducted by Lisa Arceneaux, Barry Hubbard, and David Wilkes of Engineering-Science, Inc. at the Lufkin Creosoting Company. Martyn Turner and Trish Kurl of the Texas Water Commission accompanied the Engineering-Science personnel. Mr. Danny Vines, the plant superintendent, was interviewed at his operating facility on Hwy. 69 south of Lufkin; however, the site inspection activities were conducted at the old site located inside the City of Lufkin at 1411 E. Lufkin Avenue. The interview was begun at 1:33 p.m. and covered the history and chemical handling practices at his old facility.

The Lufkin Creosoting Company (old site) is about 8 acres in size and once treated poles, posts, and dimensionalized lumber. It began operations in 1946 and was owned by 12 partners: R.E. Urwin, T.H. Ward, B.A. Thigpen, Elium Brazeal, Virgil Duke, Horace Duke, Mr. Smith, J. L. Spoton, L.M. May, H. C. Weson, D. M. Vines, and Mr. Alders. Between 1956 and 1964 Mr. Dan Vines (senior) bought the business from his partners to acquire total ownership. Before 1946 a sawmill, Southern Bell Lumber Company, occupied the site.

Another wood treating facility, Higgens Wood Treating Company, was located adjacent to the northeast corner of the site and was in operation from 1930-1973. This site was Texas Electric Coop until 1962 when the Higgens brothers bought it and changed the name to Higgens Wood Treating Company. Currently a Walmart Shopping Center is located on that site.

The Lufkin Creosoting Company was operated at the Lufkin Avenue location until 1978 when the owner closed it to move to a larger site on Hwy. 69. Equipment that had been on site included 4 treatment cylinders, 3 work tanks, 3-4 treatment tanks, 2 boilers and a surface impoundment. The cylinders and some of the tanks were sold and the work tanks were brought to the new site of Lufkin Creosoting. One of the boilers was left on site at the old location.

The surface impoundment had been used for blowdown water and was contaminated with creosote. The size of the impoundment was approximately 80' x 150' x 28". It was closed in 1973-1974 without TWC enforcement or supervision by pushing the embankment soil over the surface. Grass was observed growing over the closed impoundment.

A site reconnaissance with Mr. Vines was begun at the old site after the interview. Equipment observed on site included a boiler and 4 120-foot treatment cylinders. The cylinders were reportedly a recent purchase from the west coast and were being stored at the site. A large drainage ditch traversed the prop-

erty in an east to west direction with a portion enclosed in a culvert. The culvert was made of 6000 gallon steel diesel storage tanks welded together. Erosion channels were observed along the length of the culvert and blackened soil was observed at 3-6 inches from the surface within the channels. Black stains were seen on the sediment and grasses in the open portion of the drainage ditch. Water was flowing slowly in the ditch and had a blackish color and an oily sheen.

Around the tank farm area a 3-inch thick concrete pad was observed. No containment walls were observed and the soil on the west side of the pad was black and oily with distressed vegetation.

samples were collected from the drainage ditch and the closed impoundment. A background soil sample was collected across Lufkin Blvd. south of the site. Mr. Vines split samples at each sample location. An "upgradient" sediment sample from the drainage ditch was collected from the middle of the ditch at the east property line and inside Mr. Vines' property. As the sample was collected black oily waste surfaced and floated on the water. The downstream sediment sample was collected in the middle of the open ditch. Black oily sediment was noted in the sample at a depth of approximately 5 inches below the surface. A subsurface soil sample was collected at about 2 feet below the surface at the closed surface impoundment. At this depth a very clayey black sludge with a creosote odor was encountered.

WASTE MANAGEMENT PRACTICES

The treatment chemicals used at the site were creosote and pentachlorophenol (PCP). PCP was used in the early 1970's. The volume of creosote used was about 6,000 gallons/week with a maximum of 18,000 gallons stored on site. The facility used city water for the closed steaming process to pretreat the wood. The surface impoundment was once used for the blowdown water; then the company changed the process to recycling the wastewater in above-ground tanks. The tanks were equipped with bottom skimmers recover the creosote. The cylinders and tanks were closed once every 4-5 years and the sludge was stored on site until removed by disposers or hauled to the city dump. Mr. Vines did not know any details of the past disposers. In 1983 BFI-CECOS International removed about 10 tons of PCP sludge from a raw material storage tank (left on site). The removal requested by TDWR and was manifested (Attachment B).

ASSESSMENT AND CONCLUSIONS

The sample results included in Attachment D indicate contamination by creosote constituents in the background soil sample and upgradient sediment sample. Although the background sampling location was vegetated and appeared normal, several creosote constituents were detected in moderate concentrations. Access to this soil is not restricted as the sample was collected along a roadway and resident's fence (see Photo 7).

The concentration of creosote constituents in the upgradient sediment sample were generally about two times higher than background. This sample location was near the old creosote storage area which could have been a source of creosote contamination. The concentration of creosote constituents appeared to decrease in the drainage ditch at the west end of the site indicated by the sample results) although the soil was black and oily in appearance. Adsorption to clay and silty soil could explain the decrease of creosote concentrations in the ditch. The concentration of creosote constituents in the impoundment location was relatively low and only three compounds were detected. No pentachlorophenol was detected in any of samples.

Because of the concentration of creosote found off site (where the background sample was collected) and in the upgradient on-site sediment sample, the site is given a medium hazard ranking. A follow-up site inspection is recommended to assess the extent of creosote contamination on site (in the drainage ditch and old tank farm) and off site.